



## TECHNICAL DATASHEET

|                          |                                 |
|--------------------------|---------------------------------|
| <b>Code</b>              | IND-U6S                         |
| <b>Brief Description</b> | Humidity indicators, box of 250 |
| <b>Type</b>              | Spot 6                          |
| <b>Dimensions outer</b>  | 105 x 37 h mm                   |
| <b>Package</b>           | of 250 pieces                   |



### Description

Humidity indicators

Humidity indicators signal when a specified relative humidity is exceeded.

Signaling is done by changing the spots from brown to light blue.

- They signal the level of humidity present from 10% to 60%.
- They do not contain cobalt.
- Place the indicators inside the packages.